Survey No. HA-1767

Maryland Historical Trust State Historic Sites Inventory Form

DOE __yes __no

Magi No.

1. Nam	e (indicate pr	eferred name)		
historic Evans	Greer House Barn /Ca	arriage House		
and/or common	210 Hall Street			
2. Loca	ation			
street & number	210 Hall Street			_ not for publication
clty, town Be1		vicinity of	congressional district 1s	
state Marylan			Harford	
	sification			
Category district building(s) structure site object	Ownership public private both Public Acquisition in process being considerednot_applicable	Status _x_ occupied unoccupied work in progress Accessible _x yes: restricted _ yes: unrestricted _ no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific X transportation other:
4. Own	er of Prope	rty (give names a	nd mailing addresses	of <u>all</u> owners)
name Vernon	n T. Jones			
street & number	210 Hall Street		telephone no	.: unpublished
city, town Bel	Air	state	and zip code Maryl	and 21014
5. Loca	ation of Leg	al Description	on	
courthouse, regi	stry of deeds, etc. Har	ford County Courtho	use	liber <u>1</u> 268
street & number	Main Street			folio 756
city, town Be1	Air		state ^M	aryland
6. Repi	resentation	in Existing	Historical Surve	ys
title				
date			federal state	county loca
pository for su	rvey records			
city, town		-	state	
		· · · · · · · · · · · · · · · · · · ·		

7. Desc	cription		Survey No. HA 1767
Condition excellentX_ good fair	deteriorated ruins unexposed	Check one unalteredX altered	Check one original site moved date of move

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

 $(1+\epsilon)_{ij}$, $(1+\epsilon)_{ij}$, $(1+\epsilon)_{ij}$, $(1+\epsilon)_{ij}$, $(1+\epsilon)_{ij}$, $(1+\epsilon)_{ij}$, $(1+\epsilon)_{ij}$

8. Sign	ificance	S	urvey No. 11767
1700–1799	archeology-historic agriculture architecture art commerce	community planning	w science erature sculpture ilitary social/ usic humanitarian
Specific dates	1911-12	Builder/Architect Charles Mo	Dowell
an Appl:		A _ B _ C _ D A _ B _ C _ D _ E _ F _nationalstateloca	
support. This ba	rn has been renovate	d, but is still a contribut	ral statement of history and ting structure to the for Significance statement.

9. Major Bibliographical References

Survey No. 1/67

Larew, Marilynn, BEL AIR: The Town Through its Buildings, The Town of Bel Air and the Maryland Historical Trust, 1981.

10. Geographical I	Data		
Acreage of nominated property Quadrangle name UTM References do NOT complete U			Quadrangle scale
A Zone Easting Northing		B Zone Easting	Northing
C		D	
Verbal boundary description and justi This property occupie List all states and counties for proper	s Parcel 16 in		
state c	ode cou	nty	code
state c	ode coul	nty	code
11. Form Prepared name/title Elizabeth Lampl	Ву		
organization Robinson & Associates		date 5/3	21/1990
street & number 1710 Connecticut Av	enue, NW	telephone	202-234-2333
city or town Washington,		state DC	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House 21 State Circle

Annapolis, Maryland 21401


(301) 269-2438

Evans-Greer Barn/Carriage House 210 Hall Street #

Item 7, Description (continuation sheet)

This two-story carriage house was built in 1911-12 as part of the Evans Greer estate. According to the Evans-Greer House Maryland Historical Trust inventory form (HA-1414), the structure was constructed simultaneously with the original estate. It is oriented at the end of the long, curving drive, its principal facade being the southeast elevation. The structure is built of irregularly coursed, granite ashlar block on the ground story. The second story is sheathed in wide wooden boards. The roof is side-gabled. An original, fixed-pane, 3/3 window is to the left of the garage openings. It has a rough granite sill and a smooth granite lintel.

Recently, the structure has been renovated: two new garage doors have replaced original carriage doors at the ground level, new 1/1 double-hung windows have been installed at the second story, and new asphalt shingling covers the side-gable roof. A stairway (not original) leads from the ground to a second-story entrance on the northeast elevation.





Evans-Greet House - Barn Jarage # 88-17,7 210 Hall Stockt Quite Hodler 5/1/90 Facing northwest